



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D206-642-341BL
Job Sheet 192092



Part No: D206-642-341BL

Job Qty: 1 pcs

Part Name: Replacement Skidtube (Fits LH or RH)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 3/15/19

Job Tracking No:

Due Date: 4/19/19

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG D2650 REV.F(DEO) IPP Rev: H 05.10.11 Added D3429-1 per CHG004 KJ/CP/JLM IPP Rev:I 08-09-29 revF as per dwg DD verified by:EC Est Rev:J 09-03-02 as per DS19440 rev.a DD verified by:EC IPP rev K 10.08.03 chg ms27039-1-08 for "C" type EC verf:DD IPP Rev:L 12.11.22 now swage per ecn12-679 DD verf:JLM IPP Rev:M 14.04.25 ECN14-520 DD verf:JLM IPP REV:N 15.10.09 ADDED BL DD VERF:JLM IPP REV:O 16.01.22 PAR16-484 DD VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard Setup Hrs	Run Hrs	Workcenter/Supplier	Lead Time	Sign-off
110	Skidtubes - 1	1 pcs	4/19/19		0.00	1.58	Skidtubes - 1		
							Skidtubes - 2		
							Skidtubes - 3		
							Skidtubes - 4		
							Skidtubes - 5		
							Skidtubes - 6		
							Skidtubes - 7		
115	QC 5	1 pcs	4/19/19		0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 42		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		
							QC 5 - 30		
							QC 5 - 40		
116	QC 9	1 pcs	4/19/19		0.00	0.00	QC 9 - 10		
							QC 9 - 18		
							QC 9 - 24		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S166558



Part: D206-642-341BL

Job No: 192092

Serial No/Batch: S166558

Revision: F(deo)

Inspector:

Exp Date:

Instructions: FAA STC SA00475SE 18/10/17 TC STC SH98-4 Issue 2, EASA STC

Plex 3/15/19 1:45 PM Dart.lajeunesse.marie

P.T.O.

				QC 9 - 43	
				QC 9 - 50	
				QC 9 - 9	1904.01
120 Handfinish - 1-1 Chemical-B4B	1 pcs	4/19/19	0.00 1.17	Handfinish - 1 - 1 - B4B	
				Handfinish - 1 - 2 - B4B	
				Handfinish - 1 - 3 - B4B	
				Handfinish - 1 - 4 - B4B	
				Handfinish - 1 - 5 - B4B	
				Handfinish - 1 - 6 - B4B	
				Handfinish - 1 - 7 - B4B	
				Handfinish - 1 - 8 - B4B	
				Handfinish - 1 - 9 - B4B	
				Handfinish - 1 - 10 - B4B	D.R 19/04/02
				Handfinish - 1 - 11 - B4B	
				Handfinish - 1 - 12 - B4B	
				Handfinish - 1 - 13 - B4B	
				Handfinish - 1 - 14 - B4B	
				Handfinish - 1 - 15 - B4B	
				Handfinish - 1 - 16 - B4B	
				Handfinish - 1 - 17 - B4B	
				Handfinish - 1 - 18 - B4B	
				Handfinish - 1 - 19 - B4B	
				Handfinish - 1 - 20 - B4B	
				Handfinish - 1 - 21 - B4B	
				Handfinish - 1 - 22 - B4B	
125 QC 7	1 pcs	4/19/19	0.00 0.00	QC 7 - 10	
				QC 7 - 13	
				QC 7 - 14	
				QC 7 - 15	
				QC 7 - 17	
				QC 7 - 18	
				QC 7 - 19	
				QC 7 - 2	
				QC 7 - 28	
				QC 7 - 3	
				QC 7 - 30	
				QC 7 - 34	
				QC 7 - 36	
				QC 7 - 37	
				QC 7 - 41	
				QC 7 - 47	
				QC 7 - 48	
				QC 7 - 51	
				QC 7 - 58	
				QC 7 - 59	
				QC 7 - 60	mb67
				QC 7 - 9	
				QC 7 - 68	

130 Skidtubes - 2 - B4B	1 pcs	4/19/19	0.00 1.58	QC 7 - 50	
				QC 7 - 67	
				QC 7 - 40	
				Skidtubes - 1 - B4B	
				Skidtubes - 2 - B4B	
				Skidtubes - 3 - B4B	
				Skidtubes - 4 - B4B	
140 QC 5	1 pcs	4/19/19	0.00 0.00	Skidtubes - 5 - B4B	
				Skidtubes - 6 - B4B	
				Skidtubes - 7 - B4B	
				QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
150 Skidtubes - 3 - B4B	1 pcs	4/19/19	0.00 1.58	QC 5 - 19	
				QC 5 - 22	
				QC 5 - 24	
				QC 5 - 3	
				QC 5 - 42	
				QC 5 - 43	
				QC 5 - 49	
180 QC 5	1 pcs	4/19/19	0.00 0.00	QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	
				QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	
				QC 5 - 40	
190 Handfinish - 2-1 Pressure-B4B	1 pcs	4/19/19	0.00 1.17	Skidtubes - 1 - B4B	
				Skidtubes - 2 - B4B	
				Skidtubes - 3 - B4B	
				Skidtubes - 4 - B4B	
				Skidtubes - 5 - B4B	
				Skidtubes - 6 - B4B	
				Skidtubes - 7 - B4B	
200 Outsource - 11 - Paint	1 pcs	4/19/19		QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
				QC 5 - 19	
				QC 5 - 22	
				QC 5 - 24	
201 Spraypaint	1 pcs	4/19/19		QC 5 - 3	
				QC 5 - 42	
				QC 5 - 43	
				QC 5 - 49	
				QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	
200 Outsource - 11 - Paint	1 pcs	4/19/19		QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	
				QC 5 - 40	
				Handfinish - 2 - 1 - B4B	
				Handfinish - 2 - 2 - B4B	
				Handfinish - 2 - 3 - B4B	
200 Outsource - 11 - Paint	1 pcs	4/19/19		Handfinish - 2 - 4 - B4B	
				ATE003-VC	3

DAS
APR 12 2019 68
9-89

D.R. 19/04/15

205 QC 6 NA	1 pcs	4/19/19	0.00 0.00	QC 6 - 42	
				QC 6 - 9	
				QC 6 - 68	
				QC 6 - 61	
				QC 6 - 15	
210 QC 14	1 pcs	4/19/19	0.00 0.00	QC 14 - 2	
				QC 14 - 34	
				QC 14 - 41	
				QC 14 - 51	
				QC 14 - 58	
				QC 14 - 59	BEB. 9-89 DAS
				QC 14 - 9	
				QC 14 - 68	
				QC 14 - 40	
				QC 14 - 19	
220 Handfinish - 4-1-Assembly-B4B	1 pcs	4/19/19	0.00 1.17	Handfinish - 4 - 1 - B4B	19-4-26
				Handfinish - 4 - 10 - B4B	
				Handfinish - 4 - 11 - B4B	
				Handfinish - 4 - 12 - B4B	
				Handfinish - 4 - 13 - B4B	
				Handfinish - 4 - 14 - B4B	
				Handfinish - 4 - 15 - B4B	
				Handfinish - 4 - 2 - B4B	
				Handfinish - 4 - 3 - B4B	
				Handfinish - 4 - 4 - B4B	
				Handfinish - 4 - 5 - B4B	
				Handfinish - 4 - 6 - B4B	
				Handfinish - 4 - 7 - B4B	
				Handfinish - 4 - 8 - B4B	
				Handfinish - 4 - 9 - B4B	
230 QC 3	1 pcs	4/19/19	0.00 0.00	QC 3 - 10	
				QC 3 - 13	
				QC 3 - 15	
				QC 3 - 17	
				QC 3 - 18	
				QC 3 - 2	
				QC 3 - 28	
				QC 3 - 3	
				QC 3 - 30	
				QC 3 - 34	
				QC 3 - 36	
				QC 3 - 41	
				QC 3 - 51	
				QC 3 - 58	
				QC 3 - 59	
				QC 3 - 68	APR 26 2019 68 9-89
				QC 3 - 9	
				QC 3 - 40	
				QC 3 - 19	
240 QC 5	1 pcs	4/19/19	0.00 0.00	QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
				QC 5 - 19	

					QC 5 - 22	
					QC 5 - 24	
					QC 5 - 3	
					QC 5 - 42	
					QC 5 - 43	
					QC 5 - 49	
					QC 5 - 51	
					QC 5 - 58	DAS
					QC 5 - 68	APR 26 2019 68
					QC 5 - 9	9-89
					QC 5 - 50	
					QC 5 - 30	
					QC 5 - 40	
250	Packaging 3-1 - Stock - B4B	1	4/19/19	0.00 0.00	Packaging 3 - 1 - B4B	
	pcs				Packaging 3 - 2 - B4B	
					Packaging 3 - 3 - B4B	
					Packaging 3 - 4 - B4B	
					Packaging 3 - 5 - B4B	
					Packaging 3 - 6 - B4B	
					Packaging 3 - 7 - B4B	
					Packaging 3 - 8 - B4B	
					Packaging 3 - 9 - B4B	
					Packaging 3 - 10 - B4B	
					Packaging 3 - 11 - B4B	
					Packaging 3 - 12 - B4B	
					Packaging 3 - 13 - B4B	
					Packaging 3 - 14 - B4B	
					Packaging 3 - 15 - B4B	
					Packaging 3 - 16 - B4B	
					Packaging 3 - 17 - B4B	
					Packaging 3 - 18 - B4B	
					Packaging 3 - 19 - B4B	
					Packaging 3 - 20 - B4B	
					Packaging 3 - 21 - B4B	
					Packaging 3 - 22 - B4B	
					Packaging 3 - 23 - B4B	
					Packaging 3 - 24 - B4B	
					Packaging 3 - 25 - B4B	
					Packaging 3 - 26 - B4B	
					Packaging 3 - 27 - B4B	
					Packaging 3 - 28 - B4B	
					Packaging 3 - 29 - B4B	
					Packaging 3 - 30 - B4B	
					Packaging 3 - 31 - B4B	
					Packaging 3 - 32 - B4B	
					Packaging 3 - 33 - B4B	
					Packaging 3 - 34 - B4B	
					Packaging 3 - 35 - B4B	DAS
					Packaging 3 - 36 - B4B	21 APR 26 2019
255	DC - 1 - B4B	1	4/19/19	0.00 0.00	DC - 1 - B4B	
	pcs				DC - 2 - B4B	DAS APR 26 2019
260	QC 21 - FG	1	4/19/19	0.00 0.00	QC 21 - FG - 21	21
	pcs				QC 21 - FG - 70	DAS 9-89
					QC 21 - FG - 53	21 APR 26 2019

Part Op 110 - Skidtubes 1-Deburr Fwd edge of tube 2-Scribe "Identify Batch Number" 3-Remove ridge on inside of Fwd edge of Descriptions: tubeas per Dwg D2650 4-Weld Fwd Cap as per Dwg D2650. Use aluminum rod. Grind D2647 to fit as required. A/R Aluminum Rod m138989 5-Grind weld flush to cap on top surface only. 6-Cut aft end to length as per dwg D2650 7-Drill pilot holes using drill Jig DT8168A (A, & B) and DT8025. 8-Drill holes for wearplates using DT 8028-5. Open to Ø 0.297". 9-Open Aft Cap Hole using #6 Drill Bit 10-Open holes for Tow Ring to Ø0.625" as per Dwg D2650, D2650-5 Drilling Detail 11-Remove inner indexing ridge on aft end of skidtubeas per Dwg D2650 12- Ream holes to finished size

as per Dwg D2650, D2650-5 Drilling Detail (without cutting fluid) 13-Deburr.

115 - QC5- Inspect part completeness to step on W/O**116** - QC9- Inspect visual per QSI004- Fusion Welds**120** - Chemical Conversion Coat per QSI005 4.1**125** - QC7-Inspect Chemical Conversion Coat**130** - Skid tubes - 1- Bond D2654-5 web in place as per QSI 015 Ensure holes line up Allow 12 Hrs. cure time before cutting Start Date: 19-04-08 Time: 10:30AM Finish Date: 19-04-08 Time: 10:30PM A/R Sikaflex-2915163945 Sikaflex expiry date: 19-04-23**140** - QC5- Inspect part completeness to step on W/O**150** - Skid tubes - 1- Insert D4720-1 Spacer. Swage to 0.313" X 0.75" DP per QSI 002. Trim and grind flush per QSI 002**180** - QC5- Inspect part completeness to step on W/O**190** - Pressure Wash per QSI005 4.3/ Clean and remove all markings**200** - ISSUE PO _____ Prime and Paint DELFLEET BLUE Prime 5171227 / Blue 5150229 / Clear 5171229**205** - QC6- All purchased or subcontracted products**210** - QC14- Inspect Spray Paint**220** - HandFinish4 (Assemble as per dwg - 1-Install inserts & wearpads as per dwg D2922. Use a drop of Sikaflex inside insert holes before installing wearpad/wearplate. A/R Sikaflex-291 _____ Sikaflex expiry date: _____ 2-

Install O-Rings D2651-3 on plugs D2651-1 with Petroleum Jelly and install plugs as per Dwg D2650. Clean excess

adhesive 3-Install MS27039-4-06 Screw 4-Inspect for foreign object per QSI 024 5-Install D2646 Aft Cap and seal with SikaflexClean excess adhesive A/R Sikaflex-291 _____ Sikaflex expiry date: _____ 6- Install D2680-041

Nut Plate as per Dwg D2650 7-Wing Walk as per Dwg D2650-5 and QSI 005 4.4 Batch: _____

230 - QC3- Inspect Part Finish**240** - QC5- Inspect part completeness to step on W/O**250** - Identify and pack for shipping as per PPP D206-642-341 Location:FG083**255** - Document Control - Photocopy bluefile and create labels per PPP D206-642-341 CHG005**260** - QC21- Final Inspection - Work Order Release

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2620	Skid tube, 206 Skid tube	1 pcs (1 ea)	110-Skid tubes - 1	<u>5157984</u>
D2647	Cap	1 pcs (1 ea)	110-Skid tubes - 1	<u>5089785</u>
D2654-5	Web	1 pcs (1 ea)	130-Skid tubes - 2 - B4B	<u>5141198</u>
D4720-1	Spacer	19 pcs (19 ea)	150-Skid tubes - 3 - B4B	<u>5154519</u>
ALS4-1032-130	Rivnut	54 Ea (54 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5057257</u>
CCR264SS3-3	Cherry Rivet	2 Ea (2 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>FM137622</u>
CR3212-4-03	Cherry Rivet	2 Ea (2 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>FM137886-0</u>
D2646BL	Aft Cap	1 pcs (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5131826</u>
D2651-1BL	Plug	14 pcs (14 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>8x 5013109/65 167942</u>
D2651-3	O-Ring	14 pcs (14 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5044502</u>
D2680-041BL	Nut Plate	1 pcs (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5013112</u>
D3537-1	Wearpad <u>5174742</u>	6 pcs (6 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>2x 5171270/1</u>
D3537-3	Wearpad	1 pcs (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5114665</u>
D4956-11	Wearplate Fwd	1 pcs (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5037779</u>
D4956-23	Wearplate Center Fwd	1 pcs (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5171523</u>
D4956-35	Wearplate Aft	1 pcs (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>517257-1</u>
MS27039-1-08	Screw	2 Ea (2 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5133202-1</u>
MS27039-4-06	Screw	1 Ea (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>FM137951-1</u>
MS27039C1-08	Screw	54 Ea (54 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5167302</u>
NAS1149C0332R	Washer	54 Ea (54 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5148669</u>
NAS1149D0332J	Washer	2 Ea (2 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5123446</u>
NAS1149D0463J	Washer	1 Ea (1 ea)	220-Handfinish - 4-1-Assembly-B4B	<u>5055952</u>

Job Allocations				
Operation	Component Part	Required	Inventory	Allocated
110-Skidtubes - 1	D2620	1	10	0
	D2647	1	8	0
130-Skidtubes - 2 - B4B	D2654-5	1	11	0
150-Skidtubes - 3 - B4B	D4720-1	19	383	0
220-Handfinish - 4-1-Assembly-B4B	ALS4-1032-130	54	9,221	0
	CCR264SS3-3	2	243	0
	CR3212-4-03	2	120	0
	D2646BL	1	5	0
	D2651-1BL	14	54	0
	D2651-3	14	382	0
	D2680-041BL	1	0	0
	D3537-1	6	45	0
	D3537-3	1	22	0
	D4956-11	1	11	0
	D4956-23	1	6	0
	D4956-35	1	1	0
	MS27039-1-08	2	546	0
	MS27039-4-06	1	13	0
	MS27039C1-08	54	420	0
	NAS1149C0332R	54	5,103	0
	NAS1149D0332J	2	2,991	0
	NAS1149D0463J	1	6,901	0
Part Specifications				
Specifications could not be found.				

Plex 3/15/19 1:45 PM Dart.lajeunesse.marie

QTY -1	QTY -3	QTY -5	QTY -7	PART NUMBER	DESCRIPTION
X				D2650-1	SKIDTUBE ASSEMBLY
	X			D2650-3	SKIDTUBE ASSEMBLY
		X		D2650-5	SKIDTUBE ASSEMBLY
			X	D2650-7	SKIDTUBE ASSEMBLY
1	1	1	1	D2600-1-160	EXTRUSION
1				D2654-1	WEB
	1			D2654-3	WEB
		1		D2654-5	WEB
			1	D2654-7	WEB
1	1	1	1	D2646	AFT CAP
1	1	1	1	D2647	CAP
17	18	19	23	D2649	CROSS BOLT SPACER
16	18	14	22	D2651-1	PLUG
16	18	14	22	D2651-3	O-RING
1	1	1	1	D2680-041	NUT PLATE
2	2			D3286-1	DOUBLER
2	2			D3286-3	STUD
42	44	54	60	ALS7-1032-130	INSERT (or AKS4-1032-130, ALS4-1032-130, ALS7-1032-130)
2	2	2	2	AN960JD10L	WASHER
2	2	2	2	CCR264SS3-3	RIVET
2	2	2	2	CR3212-4-03	RIVET
2	2	2	2	MS27039-1-08	SCREW
1	1	1	1	MS27039-4-06	SCREW
1	1	1	1	AN960JD416	WASHER
52	52			CR3212-4-04	RIVET

F

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 192092 MJS
19-03-11

DEO ATTACHED

RELEASED
08-07-23/17

NOTES:


- 1) MATERIAL: N/A
- 2) FINISH: -CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
-POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3
-BLACK ANTI-SKID PAINT AS INDICATED TO 0.5 ABOVE LOCATION RIDGE PER DART QSI 005 4.4
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: N/A
- 8) WELD PER DART QSI 004
- 9) DAMAGE TOLERANCE ON FWD BEND:
THERE SHOULD BE NO VISIBLE WRINKLES IN THE BEND FROM THE GROUND TO A HEIGHT OF 5 INCHES ABOVE THE GROUND. IT IS ACCEPTABLE TO POLISH OUT GOUGES UP TO 0.020 DEEP IN THE BENT PORTION OF THE TUBE. A MAXIMUM REDUCTION IN DIAMETER OF 0.150" IS ACCEPTABLE IN THE BENT PORTION OF THE TUBE.
- 10) BOND WEB INTO OUTER TUBE WITH SIKAFLEX-241/-291 ADHESIVE PER DART QSI 015
- 11) INSERT D2651-1 PLUG C/W D2651-3 O-RING IN HOLES MARKED 'P' (BOTH SIDES OF TUBE)
- 12) DRILL Ø0.297 FOR ALS7-1032-130 INSERTS USING TEMPLATE DT8056-1 ON -1 TUBE, DT8056-3 ON -3 TUBE, DT8056-5 ON -5 TUBE, AND DT8056-7 ON -7 TUBE. INSTALL INSERTS AFTER FINISH.
- 13) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

F	DRAWING UPDATED TO CURRENT STANDARDS. SHT 6 ADDED. ALL SECTION AND DETAIL VIEWS TRANSFERRED TO SHT 6. SHT 1 IN PL PART D2649 QTY UPDATED. SHT 8 SECT C-C GRIND INSTRUCTIONS DELETED FROM NOTE 7 (SEE NCR 239).	AJS	08.08.08
E	REMOVE CBORE, CHG DRILL. ADD CHAMFER	CP	06.03.30
D	REDRAW; INCCRP. DE09136/9153/9163 MOD GROUND HANDLING ON D2650-1/-3	CP	04.05.17
C	CHANGE HOLE PATTERN AND FRONT END	DS	97.10.29
B	AS MANUFACTURED CHANGES	DS	97.06.26
A	NEW ISSUE	DS	97.03.25
REV.	DESCRIPTION	BY	DATE
DESIGN	DS	DART AEROSPACE USA, INC PORT HADLOCK, WA	
DRAWN	AJS		
CHECKED		DRAWING NO.	REV. F
MFG. APPR.		D2650	SHEET 1 OF 6
APPROVED		TITLE	SCALE
DE APPR.		206/407 SKIDTUBE ASSEMBLIES	NTS
DATE	08.08.08	COPYRIGHT © 1997 BY DART AEROSPACE USA, INC. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.	




DEO ATTACHED
RELEASED
880922/114

DESIGN	DS	DART AEROSPACE USA, INC	
DRAWN	AJS	PORT HADLOCK, WA	
CHECKED		DRAWING NO.	REV. F
MFG. APPR.		D2650	SHEET 2 OF 6
APPROVED		TITLE	SCALE
DE APPR.		206/407 SKIDTUBE ASSEMBLIES	NTS
DATE	08.08.08	COPYRIGHT © 1997 BY DART AEROSPACE USA, INC THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL, AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR CONTENTS COMMUNICATED TO ANY OTHER PERSON WITHOUT THE WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.	




D2650-3 BENDING/DRILLING DETAIL




D2650-3 ASSEMBLY/FINISHING DETAIL

DESIGN	DS	DART AEROSPACE USA, INC	
DRAWN	AJS	PORT HADLOCK, WA	
CHECKED		DRAWING NO.	REV. F
MFG. APPR.		D2650	SHEET 3 OF 6
APPROVED		TITLE	SCALE
DE APPR.		206/407 SKIDTUBE ASSEMBLIES	NTS
DATE	08.08.08	COPYRIGHT © 1997 BY DART AEROSPACE USA, INC THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.	



D2650-5 BENDING/DRILLING DETAIL




D2650-5 ASSEMBLY/FINISHING DETAIL

DEO ATTACHED



RELEASED

DESIGN	DS	DART AEROSPACE USA, INC	
DRAWN	AJS	PORT HADLOCK, WA	
CHECKED		DRAWING NO.	REV. F
MFG. APPR.		D2650	SHEET 4 OF 6
APPROVED		TITLE	SCALE
DE APPR.		206/407 SKIDTUBE ASSEMBLIES	NTS
DATE	08.08.08	COPYRIGHT © 1997 BY DART AEROSPACE USA, INC	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.			




DETAIL A
SCALE 2X
C2-2
D7-2
C2-3
D7-3
C2-4
D7-4
C2-5
D6-5


DETAIL B
SCALE 2X
C3-2
C3-3



DETAIL D
FOR Ø0.375 HOLES ONLY
SCALE 3X
B4-2
B4-3
B4-4
B4-5



DETAIL E
SCALE 2X
B2-2
B2-3
B1-4
B1-5



DETAIL F
SCALE NONE
B8-2
B8-3
B8-4
B8-5

- DETAIL F NOTES:**
1. CUT TUBE LEVEL
 2. REMOVE RIDGE ON FWD SIDE
 3. LOCATE D2647 (TRIM AS NECESSARY)
 4. WELD D2647 IN PLACE PER DART QSI 004
 5. GRIND FLUSH
 6. RIVET D2680-041 NUT PLATE IN PLACE

NOTE: MASK THREADS IN D2680-041 PRIOR TO FINISH

RELEASED

DEO ATTACHED

DESIGN	DS	DART AEROSPACE USA, INC	
DRAWN	AJS	PORT HADLOCK, WA	
CHECKED		DRAWING NO.	REV. F
MFG. APPR.		D2650	SHEET 6 OF 6
APPROVED		TITLE	SCALE
DE APPR.		206/407 SKIDTUBE ASSEMBLIES	NTS
DATE	08.08.08	COPYRIGHT © 1997 BY DART AEROSPACE USA, INC	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMBINATION TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.			

DRAWING NO. D2650	TITLE 206/407 SKIDTUBE ASSEMBLIES	REV. F	DART AEROSPACE LTD ENGINEERING ORDER		D.E.O. NO. D2650-F-1	SHEET NO. SHEET 1 OF 1	SCALE NTS
DRAWN <i>JP</i>	CHECKED <i>A.P.</i>	MFG. APPR. <i>AA</i>	APPROVED <i>##</i>		DE APPR. <i>##</i>		
DATE 12.10.12	DATE 12.10.22	DATE 12.10.22	DATE 12.10.22		DATE 12.10.22		

PURPOSE:

CHANGE C'BORED WELDED CROSSBOLT SPACERS TO SWAGED SPACERS

CHANGE:

PARTS LIST IS AMENDED AS FOLLOWS:

IS:


QTY	QTY	QTY	QTY	PART NUMBER	DESCRIPTION
-1	-3	-5	-7		
1	1	0	0	D2649	CROSS BOLT SPACER
16	17	19	23	D4720-1	SPACER

WAS:

17	18	19	23	D2649	CROSS BOLT SPACER
----	----	----	----	-------	-------------------

ADD DETAIL G BELOW, WHICH IS THE SAME SECTION VIEW AS DETAIL D OF DWG.


C'BORED HOLES ARE **NOW SWAGED** PER DETAIL G BELOW. FOR THE Ø0.375 HOLE THAT IS NOT C'BORED, WELD PER DETAIL D OF DWG (SEE AMENDED DETAIL B FOR REFERENCE).



DETAIL B

AMENDMENT TO DETAIL B
NOT TO SCALE

RELEASED
2012-11-16
MP



DETAIL G

FOR Ø0.375 HOLES ONLY
FOR HOLES THAT ARE CURRENTLY C'BORED ONLY
NOT TO SCALE

AFTER DRILLING AND BENDING ASSEMBLY
PERFORM THE FOLLOWING FOR Ø0.375 HOLES THAT ARE
CURRENTLY C'BORED:

1. INSERT D4720-1 SPACER, 16 PL (-1) OR 17 PL (-3)
OR 19 PL (-5) OR 23 PL (-7)
2. SWAGE TO Ø0.313 X 0.75 DP PER QSI 002
3. TRIM / GRIND FLUSH PER QSI 002

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No.

Route update only ☐

Job: <u>192092</u> Part No. <u>2206642-341BK</u>		DISPOSITION Rework ☒ Scrap ☐ Use-as-is ☐		DEPARTMENT/PROCESS Skid-tube ☒ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☒ Water Jet ☐ Supplier Quality ☐							
Date: <u>19/3/21</u>		Sequence #: <u>118</u>		QTY Affected: <u>1</u>		MRB (QSI042) INSP <u>12</u> <u>GP</u> <u>19/3/21</u>					
Description Work Order Deviation				Disposition							
Dwg calls for $\phi 0.625$ TOW RING HOLE.				DRILL TOW RING HOLE $\phi 0.640$ Ref. dwg D3274 Rev. G. <u>GP</u> <u>19/3/21</u>							
								Completed By <u>GP</u> <u>19/3/21</u>			
								Lead hand / Supervisor <u>JPW</u> <u>19-07-22</u>			
QC / QA Coordinator <u>DAS</u> <u>68</u> <u>9-89</u> JUL 22 2019											
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☒ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☒ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread									
		Other/Details:									